

HUNTING BRONZE BUSHINGS

| <u>I.D.</u> | <u>X</u> | <u>O.D.</u> | <u>X</u> | <u>LENGTH</u> | <u>PART #</u> |
|-------------|----------|-------------|----------|---------------|---------------|
| 1/8 | x | 3/16 | x | 1/2 | P12-4 |
| | x | 1/4 | x | 1/2 | P13-4 |
| 3/16 | x | 1/4 | x | 1/2 | P18-4 |
| | x | 5/16 | x | 3/4 | P19-6 |
| | x | 3/8 | x | 3/4 | P20-6 |
| 1/4 | x | 5/16 | x | 3/4 | P25-6 |
| | x | 3/8 | x | 1 | P26-8 |
| | x | 7/16 | x | 1 | P27-8 |
| | x | 1/2 | x | 1 | P28-8 |
| 5/16 | x | 3/8 | x | 3/4 | P31-6 |
| | x | 3/8 | x | 1 | P31-8 |
| | x | 7/16 | x | 1 | P32-8 |
| | x | 1/2 | x | 1 | P33-8 |
| 3/8 | x | 7/16 | x | 1 | P37-8 |
| | x | 1/2 | x | 1 | P38-8 |
| | x | 9/16 | x | 1 | P39-8 |
| | x | 5/8 | x | 1 | P40-8 |
| | x | 3/4 | x | 1 | P41-8 |
| 7/16 | x | 9/16 | x | 1 | P43-8 |
| | x | 5/8 | x | 1 | P44-8 |
| | x | 11/16 | x | 1 | P45-8 |
| 1/2 | x | 5/8 | x | 3/4 | P50-6 |
| | x | 5/8 | x | 1 | P50-8 |
| | x | 11/16 | x | 3/4 | P51-6 |
| | x | 11/16 | x | 1 | P51-8 |
| | x | 3/4 | x | 1 | P52-8 |
| | x | 13/16 | x | 1 | P53-8 |
| | x | 7/8 | x | 1 | P54-8 |
| | x | 1 | x | 1 | P55-8 |
| 9/16 | x | 11/16 | x | 1 | P56-8 |
| | x | 3/4 | x | 1 | P57-8 |
| | x | 13/16 | x | 1 | P58-8 |
| 5/8 | x | 3/4 | x | 1 | P62-8 |
| | x | 13/16 | x | 1 | P63-8 |
| | x | 7/8 | x | 1 | P64-8 |
| | x | 1 | x | 1 | P66-8 |
| 11/16 | x | 7/8 | x | 1 | P68-8 |

BUNTING BRONZE BUSHINGS

| <u>I.D.</u> | <u>X</u> | <u>O.D.</u> | <u>X</u> | <u>LENGTH</u> | <u>PART #</u> |
|-------------|----------|-------------|----------|---------------|---------------|
| 3/4 | x | 7/8 | x | 1 | P75-8 |
| | x | 15/16 | x | 1 | P76-8 |
| | x | 1 | x | 1 | P77-8 |
| | x | 1 | x | 1-1/2 | P77-12 |
| | x | 1-1/8 | x | 1 | P78-8 |
| | x | 1-1/4 | x | 1 | P79-8 |
| 7/8 | x | 1 | x | 1 | P87-8 |
| | x | 1 | x | 1-1/2 | P87-12 |
| | x | 1-1/16 | x | 1 | P88-8 |
| | x | 1-1/8 | x | 1 | P89-8 |
| | x | 1-1/4 | x | 1 | P90-8 |
| 15/16 | x | 1-3/16 | x | 1-1/4 | P93-10 |
| | x | 1-1/4 | x | 1-1/4 | P94-10 |
| 1 | x | 1-1/8 | x | 1-1/4 | P100-10 |
| | x | 1-3/16 | x | 1-1/4 | P101-10 |
| | x | 1-1/4 | x | 2 | P102-16 |
| | x | 1-5/16 | x | 1-1/2 | P103-12 |
| | x | 1-3/8 | x | 1-1/2 | P104-12 |
| | x | 1-1/2 | x | 1-1/2 | P105-12 |
| 1-1/8 | x | 1-1/4 | x | 1-1/4 | P112-10 |
| | x | 1-1/4 | x | 1-1/2 | P112-12 |
| | x | 1-3/8 | x | 1-1/2 | P114-12 |
| | x | 1-1/2 | x | 1-1/2 | P115-12 |
| 1-1/4 | x | 1-1/2 | x | 1-1/2 | P125-12 |
| | x | 1-1/2 | x | 2-1/2 | P125-20 |
| | x | 1-5/8 | x | 1-1/2 | P126-12 |
| 1-3/8 | x | 1-5/8 | x | 1-1/2 | P137-12 |
| 1-1/2 | x | 1-3/4 | x | 1-1/2 | P150-12 |
| | x | 1-7/8 | x | 1-1/2 | P152-12 |
| | x | 2 | x | 3 | P153-24 |
| 1-5/8 | x | 1-7/8 | x | 1-1/2 | P162-12 |
| | x | 1-7/8 | x | 2 | P162-16 |
| | x | 2 | x | 2 | P163-16 |
| 1-3/4 | x | 2 | x | 1-1/2 | P175-12 |
| 2 | x | 2-1/4 | x | 2 | P200-16 |